


<b>Asset No</b> : 174 - Excavator - Excavator	✓ OK   ✗ Requires attention
<b>Registration No</b> :	<b>Date</b> : 02/10/2024 09:35:28
<b>Make &amp; Model</b> :	<b>Equipment ID</b> : EX161

No.	Item Checked	Status	No.	Item Checked	Status
<b>General</b>					
1	Wipers & washers	✓	5	Working lights	✓
2	Windscreen/Windows/Mirrors	✓	6	Flashing lights	✓
3	<b>Tail lights/Indicators</b>	✗	7	Identification signage	✓
4	Headlights	✓			
<b>Safety</b>					
8	Emergency stop functioning	✓	14	Reverse Alarm	✓
9	Tags & locks	✓	15	Horn	✓
10	Isolation & lockouts	✓	16	<b>First aid kit</b>	✗
11	Seating & seatbelts	✓	17	Fire extinguisher	✓
12	Safety guards	✓	18	Tires	✓
13	Two way radio	NA			
<b>Maintenance</b>					
19	Grease & lubrication levels	✓	25	Brake plus park brake	✓
20	Fuel Pumps/Fuel Tank	✓	26	Hydraulic lines & connections	✓
21	Control panel/Gauges/Levers	✓	27	Implement(Bucket)	✓
22	Tracks & Wheels	✓	28	Vehicle condition	✓
23	Undercarriage	✓	29	Air conditioning	NA
24	Pins & bushes	✓	30	Unusual noise from engine	✓

Titles	Details
Hours	24
Site Name	16 McDougal street Milton
Shift	Morning
Operator Name	John

Titles	Details
Operator Signature	

## Findings and Comments

Type / Item Checked	Comments	Attachments
<b>General :</b> Tail lights/Indicators	Left indicator is not working.	
<b>Safety :</b> First aid kit	First aid kit required.	